

-58/17

=

=

-

:

I	3	
II	5	
III	5	
IV	6	
V	8	
VI			
75.	76.		
	. 77.	9
VII		14
VIII	O	24
IX		27
X			43
XI		44

29,
: www.gsp.co.rs

55., 57. 60.

68/15) -

(

124/12, 14/15

29

-58/17

(: 42123410 -)

1:

1.	42123410 -	TURBOPUNJAC, MOT.447hLA O345,IK103 K-31/H2D
2.	42123410 -	TURBOPUNJAC, MOT.457hLA A537.3 SCHWITZER S300
3.	42123410 -	TURBOPUNJAC, MOT.D2066 LOH01 K29 SA LIMOM
4.	42123410 -	TURBOPUNJAC, MOTORA D0836 LOH02 HOLSET HX40W
5.	42123410 -	TURBOPUNJAC, MOTORA D2866 LUH22 SCHWITZER S3B
6.	42123410 -	TURBOPUNJAC, MOTORA D2866 LUH24 SCHWITZ. S400

2:

IK218M

1.	42123410 -	TURBOPUNJAC, VISOKOG PRITISKA MOT.2066 LUH48
2.	42123410 -	TURBOPUNJAC, NISKOG PRITISKA MOT.D2066 LUH48
3.	42123410 -	TURBOPUNJAC, SOLARIS U18

4:

1.	42123410 -	VRATILO, TURBINSKO TURBOP.K29 D2066 LOH01
2.	42123410 -	VRATILO, TURBINSKO TURBOP.S3B D2866 LUH22

5:

1.	42123410 -	SET, DELOVA TURBOPUNJACA HX40W D0836 LOH02
2.	42123410 -	SET, DELOVA TURBOP.K29/K31 447HLA O345/IK103
3.	42123410 -	SET, DELOVA TURBOPUNJACA S300 OM457HLA
6.	42123410 -	KARIKA, TURBINE (STD/+0.508) TURBOPUNJ.T04E38
7.	42123410 -	KUCISTE, LEZAJA TURBOPUNJ.S3B D2866 LUH22
8.	42123410 -	KOLO, KOMPRESORSKO TURBOP.K29 D2066 LOH01
9.	42123410 -	TURBOKOMPRESOR, MOTORA CUMMINS HOLSET HX40W

(. 75.)

(. 76.)

77.

1.

www.gsp.co.rs.

a

5 ()

011/366-4087

58/17",

29, 11000
e-mail milena.martinovic@gsp.co.rs,

07 15

3 ()

«

06.04.2017. (

11,00

-58/17».

e-mail).

06.04.2017.

10,30

29, 11000

06.04.2017.

11,00

29, 11000

25

40

II

1.

" " :
 : , 29,
 : www.gsp.co.rs : SR100049398
 : 07022662
 : 4931

2.

32.

3.

4.

5.

6.

: milena.martinovic@gsp.co.rs,

III

-58/17

(: 42123410 -)

1:

1.	42123410 -	TURBOPUNJAC, MOT.447hLA O345,IK103 K-31/H2D
2.	42123410 -	TURBOPUNJAC, MOT.457hLA A537.3 SCHWITZER S300
3.	42123410 -	TURBOPUNJAC, MOT.D2066 LOH01 K29 SA LIMOM
4.	42123410 -	TURBOPUNJAC, MOTORA D0836 LOH02 HOLSET HX40W
5.	42123410 -	TURBOPUNJAC, MOTORA D2866 LUH22 SCHWITZER S3B
6.	42123410 -	TURBOPUNJAC, MOTORA D2866 LUH24 SCHWITZ. S400

2:

IK218M

1.	42123410 -	TURBOPUNJAC, VISOKOG PRITISKA MOT.2066 LUH48
2.	42123410 -	TURBOPUNJAC, NISKOG PRITISKA MOT.D2066 LUH48

3.

42123410 -

TURBOPUNJAC, SOLARIS U18

4:

1.	42123410 -	VRATILO, TURBINSKO TURBOP.K29 D2066 LOH01
2.	42123410 -	VRATILO, TURBINSKO TURBOP.S3B D2866 LUH22

5:

1.	42123410 -	SET, DELOVA TURBOPUNJACA HX40W D0836 LOH02
2.	42123410 -	SET, DELOVA TURBOP.K29/K31 447HLA O345/IK103
3.	42123410 -	SET, DELOVA TURBOPUNJACA S300 OM457HLA

6.

42123410 -

KARIKA, TURBINE (STD/+0.508) TURBOPUNJ.T04E38

7.

42123410 -

KUCISTE, LEZAJA TURBOPUNJ.S3B D2866 LUH22

8.

42123410 -

KOLO, KOMPRESORSKO TURBOP.K29 D2066 LOH01

9.

42123410 -

TURBOKOMPRESOR, MOTORA CUMMINS HOLSET HX40W

IV

()

1:					
				J.M.	
1.	109390801	TURBOPUNJAC, MOT.447hLA O345,IK103 K-31/H2D	5331.970.6800 KKK A.005.096.35.99 Mercedes 5331.988.6800 KKK		2
2.	109766001	TURBOPUNJAC, MOT.457hLA A537.3 SCHWITZER S300	A.008.096.79.99 Mercedes A.006.096.49.99 Mercedes 316535 SCHWITZER		6
3.	114242901	TURBOPUNJAC, MOT.D2066 LOH01 K29 SA LIMOM	5329.970.7110 KKK 51.09100.7694 MAN 51.09100.7026 MAN		14
4.	109104201	TURBOPUNJAC, MOTORA D0836 LOH02 HOLSET HX40W	359.7183 HOLSET 51.09100.7580 MAN		4
5.	109434301	TURBOPUNJAC, MOTORA D2866 LUH22 SCHWITZER S3B	51.09100.7401 MAN S3B 315107 SCHWITZER 51.09101.7233 MAN		10
6.	109010001	TURBOPUNJAC, MOTORA D2866 LUH24 SCHWITZ. S400	317602 SCHWITZER 51.09100.7491 MAN		6

2: IK218M					
				J.M.	
1.	116660301	TURBOPUNJAC, VISOKOG PRITISKA MOT.2066 LUH48	51.09100.7846 MAN 51.09101.7061 MAN KKK53269707106		2
2.	116733201	TURBOPUNJAC, NISKOOG PRITISKA MOT.D2066 LUH48	51.09100.7808 MAN KKK53299707200 KKK53299887200		2

				J.M.	
3.	120125501	TURBOPUNJAC, SOLARIS U18	0120-301-818 SOLARIS 3774515 Holset		2

4:					
				J.M.	
1	115055301	VRATILO, TURBINSKO TURBOP.K29 D2066 LOH01	5329-120-5026 KKK		3
2	115049901	VRATILO, TURBINSKO TURBOP.S3B D2866 LUH22	316194 SCHWITZER		3

5:					
				J.M.	
1	114979201	SET, DELOVA TURBOPUNJACA HX40W D0836 LOH02	1153-035-750 MELETT 3575169 SCHWITZER	set	10
2	114983001	SET, DELOVA TURBOP.K29/K31 447HLA O345/IK103	5331-711-0005 KKK 5331-711-0001 KKK 1301-031-755 MELETT	set	10
3	114984901	SET, DELOVA TURBOPUNJACA S300 OM457HLA	1253-300-750 MELETT 318393 SCHWITZER	set	10

				J.M.	
6.	115025101	KARIKA, TURBINE (STD/+0.508) TURBOPUNJ.T04E38	1100-040-183 Melet		15
7.	115048001	KUCISTE, LEZAJA TURBOPUNJ.S3B D2866 LUH22	316206 SCHWITZER		3
8.	115056101	KOLO, KOMPRESORSKO TURBOP.K29 D2066 LOH01	5329-123-2236 KKK		3
9.	455928201	TURBOKOMPRESOR, MOTORA CUMMINS HOLSET HX40W	3536058 Holset		1

_____ :

1-3 9

24 a

12

_____ :

30



- (
-)
- (,)
-
-



-
-
-
-
-

10

30

-
- a, a a
- :

-
-
-
-
-
- () , ... () .
-

-
- () ,

V

: _____

: _____

: _____

(), _____ () _____

-58/17

						/
						()
1						
2						
3						
...						

(_____) () .

-58/17

(06.04.2017.) .

VI

75. 76.

. 77.

75.)

(. 77. ,

1. je / /

2.

/ / / /

e,

e,

3.

/ /

(

)

2. 3. 2 ()
06.02.2017.



()

1. / /

e,

e,

2. / /

1. 2. 2 ()
06.02.2017.



1. :

)

(

),

(

_____ :
 _____ () :

 _____ (2014., 2015. 2016.).

 _____ :
 _____ :

2. _____ 1-3 9:

1. _____ / _____
 / _____ MAN, MERCEDES, CUMMINS DAF (/
 MAN, MERCEDES, CUMMINS DAF).
 /

_____ 5
 _____ a/
 _____ (, , ;
)

_____ 3
 _____ (06.04.2017.) _____
 _____ () .

2. _____

3. _____ 4-8:

1. _____ " " _____ (SCHWITCER, KKK, (MELETT) -
 / _____ () .

_____ 5

) (a/ ;

(06.04.2017.) 3

().

2. _____

): (

VI.

78. 5.

75. 1. 1, 2 4 77. 1. 1, 2 4

), (. 77

5
75. 76.
79. 3.

(6) - ()

5%

3

3

()

18.2.

6

5%

30

18.2.

VII

1.

1.1.

(. 75. 76.),

77.

1.2.

. 77.

1.3.

. 75. 76.

1.4.

. 79. . 3.

1.5.

78.

5.

75.

1.

1., 2.

4.

1.6.

1.7.

1.8.

. 77.

1.9.

1.

50%,

1.10.

1.11.

75.

(

1., 2.

4.).

1.12.

77.

1.

(

1., 2.

4.)

5.

1.13.

75.

10 %

1.

5.

1.14.

1.15.

1.16.

(1)
 77. 75. 1. 1., 2. 4. 76. 75. 1. 5.

1.17.

1)

2)

1.18.

1.19.

1.20.

1.21.

2.

2.1.

2.2.

2.3.

63. 2.

4087 «
milena.martinovic@gsp.co.rs,

5 ()
 29, 11000
 -58/17»,

+381 11 366
 e-mail

3 ()

2.4.

2.5.

2.6.

3.

3.1.

3.2.

() ,

(7

)

3.3. ()

15)

3.4.

4.

4.1.

4.2.

4.3.

4.4.

4.5.

(.4.4), 87. 5.

4.6.

-58/17".

-58/17".

4.7.

).

5.

5.1.

5.2.

5

6.

6.1.

).

7.

7.1.

7.2.

7.3.

8.

8.1.

. 93. 1.

()

8.2.

8.3.

8.4.

8.5.

9.

9.1.

92.

1.

9.2.

9.3.

9.2

92.

3.

5

9.4.

10.

10.1.

(2

-

_____):

I. 2

(

),

II.

(

)

11.

11.1.

(1)

(2)

(3)

(4)

(5)

11.2.

11.3.

(6)

(7)

_____)

(8)

(9)

(10)

11.4.

11.5.

11.6.

12.

12.1.

12.2.

15.

13.

13.1.

(

:

13.2.

13.3.

63. 2.

13.4.

13.5.

od
40

13.6.

149. 3. 4.

13.7.

13.8.

13.9.

13.10. 36. 1. 3)

13.11.

13.9.

13.12.

151.

13.13.

151.

13.14. 1.,

151. 2.

13.15.

156.

: 840-30678845-06

- 120.000,00

120.000.000,00 ;

- 0,1 %

120.000.000,00

: 153 253; : -58/17; : ;
-58/17; :

13.16.

<http://www.kjn.gov.rs/ci/uputstvo-o-uplati-republicke-administrativne-takse.html>.

14.

14.1.

5 %

. 86. 4.

14.2.

14.3.

14.4.

(. . . 33/2013).

15.

15.1.

-

-

-

75. 76.

15.2.

()

« ».

15.3.

15.4.

15.5.

15.6.

15.7.

15.8.

15.9.

15.10.

16.

16.1.

16.2.

()

16.3.

(), a

(5 7

).

16.4.

17.

17.1.

17.2.

/

17.3.

17.4.

17.5.

18.

18.1.

18.2.

18.3.

-
-
-
-
-

18.4.

2.

18.5.

18.6.

19.

19.1.

19.2.

19.3.

19.4.

5%

3

19.5.

19.6.

20.

20.1.

21.

21.1.

82.

1)

. 23. 25.

2)

3)

4)

21.2.

1.

1)

2)

3)

4)

5)

6)

7)

21.3.

(

21.2.

2. 1)

)

22.

22.1.

(,) ,

29, 11000

+381 11 366-

4087.

23.

23.1.

5%

5.000.000,00

10.000.000,00

23.2.

23.3.

23.4.

24.
24.1.

x

24.2.

24.3.

(10%)
30

10%

30

()

),

(

10 %

7

24.4.

()

5%
30

a

30

5%

a

()

5 %

7

VIII

O

1-8

1)

/ /

- 1

- 1.

1

(

). 1

(),

(¹ 1 -

),

, () 1

1)

2)

2)

- 2

(

) -

-

(,)

(..)

)

-a.

)

45

45

45

)

30

) ()⁴⁰ ()

) 24 a 1-3 9, a
12

3) - 3 (3) 12.
(86/15).

1) () - ;
2)

(, ,). (')

(3)
115. 2. (3,

).
- : 1,
- - 2,
- - 3, ()
- ...).
- - 4,
- () - 5,
- - (6,) - 7,
- - 8,
- - 9,

3
' - 3.

3 3

4) - 4

- 4,

4

5)

5

5.

6)

6

(6.

) -

(

)

(

)

3

5%

)

6

5%

7)

7

7.

).

7

8)

B

8

(1

),

(4)

6 (

B

(

).

IX

/ /	1
-----	---

()	
(, ,)	
/ ()	
(...) -	
() , () , ...),	
) - (; ; ; ; ;	
()	
(: () , " ") , 1)	
:	

1)

			/					
1	109390801	TURBOPUNJAC, MOT.447hLA O345,IK103 K- 31/H2D	5331.970.6800 KKK A.005.096.35.99 Mercedes 5331.988.6800 KKK		2			
2	109766001	TURBOPUNJAC, MOT.457hLA A537.3 SCHWITZER S300	A.008.096.79.99 Mercedes A.006.096.49.99 Mercedes 316535 SCHWITZER		6			
3	114242901	TURBOPUNJAC, MOT.D2066 LOH01 K29 SA LIMOM	5329.970.7110 KKK 51.09100.7694 MAN 51.09100.7026 MAN		14			
4	109104201	TURBOPUNJAC, MOTORA D0836 LOH02 HOLSET HX40W	359.7183 HOLSET 51.09100.7580 MAN		4			
5	109434301	TURBOPUNJAC, MOTORA D2866 LUH22 SCHWITZER S3B	51.09100.7401 MAN S3B 315107 SCHWITZER 51.09101.7233 MAN		10			
6	109010001	TURBOPUNJAC, MOTORA D2866 LUH24 SCHWITZ. S400	317602 SCHWITZER 51.09100.7491 MAN		6			
					1	-		

2:

IK218M

			/					
1	116660301	TURBOPUNJAC, VISOKOG PRITISKA MOT.2066 LUH48	51.09100.7846 MAN 51.09101.7061 MAN KKK53269707106		2			
2	116733201	TURBOPUNJAC, NISKOG PRITISKA MOT.D2066 LUH48	51.09100.7808 MAN KKK53299707200 KKK53299887200		2			
					2	-		

			/					
3.	120125501	TURBOPUNJAC, SOLARIS U18	0120-301-818 SOLARIS 3774515 Holset		2			

4:

			/						
1	115055301	VRATILO, TURBINSKO TURBOP.K29 D2066 LOH01	5329-120-5026 KKK		3				
2	115049901	VRATILO, TURBINSKO TURBOP.S3B D2866 LUH22	316194 SCHWITZER		3				
4									-

5:

			/						
1	114979201	SET, DELOVA TURBOPUNJACA HX40W D0836 LOH02	1153-035-750 MELETT 3575169 SCHWITZER	set	10				
2	114983001	SET, DELOVA TURBOP.K29/K31 447HLA O345/IK103	5331-711-0005 KKK 5331-711-0001 KKK 1301-031-755 MELETT	set	10				
3	114984901	SET, DELOVA TURBOPUNJACA S300 OM457HLA	1253-300-750 MELETT 318393 SCHWITZER	set	10				
5									-

			/						
6.	115025101	KARIKA, TURBINE (STD/+0.508) TURBOPUNJ.T04 E38	1100-040-183 Melet		15				
7.	115048001	KUCISTE, LEZAJA TURBOPUNJ.S3B D2866 LUH22	316206 SCHWITZER		3				
8.	115056101	KOLO, KOMPRESORSKO TURBOP.K29 D2066 LOH01	5329-123-2236 KKK		3				
9.	455928201	TURBOKOMPRES OR, MOTORA CUMMINS HOLSET HX40W	3536058 Holset		1				

		2 3/3
--	--	----------

--	-------

()	_____
-----	-------

()	45
-----	----

() 1-3 9	_____ a
-----------	---------

() 4-8	_____
---------	-------

--	--

2.

...

1.
2.
3.
4.
5.
6.
7.

											3
--	--	--	--	--	--	--	--	--	--	--	---

1	2	3	4				5	6	7	8	9

	4
--	---

()::

		() ⁻	() ⁻
(-):			
(-):			

:

		() ⁻	() ⁻
(-):			
(-):			

: 88.

	5
--	---

B

82. 1. 2.

	6
--	---

57/89, (" . 46/96) " . 104/46 18/58, " " . 16/65, 54/70 (" . 139/2014)

:	
:	
:	
:	

-

-

:

" , , 29 (:)

()

5%

(:)

58/17, 35. 1. 1. ,

5%

" , ' 29, .

-

-

-

-

:

-


	7
--	---

-

-

(

).



B

1. _____, (_____)
 _____ (_____) / _____, (_____),
 _____ (_____)

..... (_____)
 (_____)
 (_____)

2. _____, _____, _____ " _____ " :
 _____, _____, _____ (_____)

_____ : _____ : _____ (_____ : _____),
 _____ -58/17 17.03.2017.

XIV-58/___ ____.2017.

1.

(_____ : _____),

2.

(_____),

15 %

.(_____ 1,5 6).

3.

(_____), ... (_____).
 (_____ , _____)

4.

XIV-58/___ ___.2017.

1)

			/					
1	109390801	TURBOPUNJAC, MOT.447hLA O345,IK103 K- 31/H2D	5331.970.6800 KKK A.005.096.35.99 Mercedes 5331.988.6800 KKK		2			
2	109766001	TURBOPUNJAC, MOT.457hLA A537.3 SCHWITZER S300	A.008.096.79.99 Mercedes A.006.096.49.99 Mercedes 316535 SCHWITZER		6			
3	114242901	TURBOPUNJAC, MOT.D2066 LOH01 K29 SA LIMOM	5329.970.7110 KKK 51.09100.7694 MAN 51.09100.7026 MAN		14			
4	109104201	TURBOPUNJAC, MOTORA D0836 LOH02 HOLSET HX40W	359.7183 HOLSET 51.09100.7580 MAN		4			
5	109434301	TURBOPUNJAC, MOTORA D2866 LUH22 SCHWITZER S3B	51.09100.7401 MAN S3B 315107 SCHWITZER 51.09101.7233 MAN		10			
6	109010001	TURBOPUNJAC, MOTORA D2866 LUH24 SCHWITZ. S400	317602 SCHWITZER 51.09100.7491 MAN		6			
							1	-

2:

IK218M

			/					
1	116660301	TURBOPUNJAC, VISOKOG PRITISKA MOT.2066 LUH48	51.09100.7846 MAN 51.09101.7061 MAN KKK53269707106		2			
2	116733201	TURBOPUNJAC, NISKOG PRITISKA MOT.D2066 LUH48	51.09100.7808 MAN KKK53299707200 KKK53299887200		2			
							2	-

			/					
3.	120125501	TURBOPUNJAC, SOLARIS U18	0120-301-818 SOLARIS 3774515 Holset		2			

4:

			/						
1	115055301	VRATILO, TURBINSKO TURBOP.K29 D2066 LOH01	5329-120-5026 KKK		3				
2	115049901	VRATILO, TURBINSKO TURBOP.S3B D2866 LUH22	316194 SCHWITZER		3				
4									-

5:

			/						
1	114979201	SET, DELOVA TURBOPUNJACA HX40W D0836 LOH02	1153-035-750 MELETT 3575169 SCHWITZER	set	10				
2	114983001	SET, DELOVA TURBOP.K29/K31 447HLA O345/IK103	5331-711-0005 KKK 5331-711-0001 KKK 1301-031-755 MELETT	set	10				
3	114984901	SET, DELOVA TURBOPUNJACA S300 OM457HLA	1253-300-750 MELETT 318393 SCHWITZER	set	10				
5									-

			/						
6.	115025101	KARIKA, TURBINE (STD/+0.508) TURBOPUNJ.T04 E38	1100-040-183 Melet		15				
7.	115048001	KUCISTE, LEZAJA TURBOPUNJ.S3B D2866 LUH22	316206 SCHWITZER		3				
8.	115056101	KOLO, KOMPRESORSKO TURBOP.K29 D2066 LOH01	5329-123-2236 KKK		3				
9.	455928201	TURBOKOMPRES OR, MOTORA CUMMINS HOLSET HX40W	3536058 Holset		1				

(: _____), _____ (: _____)

e

5.

3

5%

- (- /)

(_____)

10

6.

1 ()

()

1.

()

10%

4.

30

30

10%

6.

5.

a

()

()

10%

7

7.

1 ()

1.

()

5%

4.

30

:

5%

30

7. 4.

a

()

5 %

7

8.

45

9.

2.
1 %

5%

K

10.

(_____) _____

(_____) _____

10

30

11.

29.

()

()

10

12.

() ,

a

13.

5%

14.

15.

16.

17.

5 ()

7 ()

2 () ,

<hr/>		<hr/>
-------	--	-------

X

57/89, " .46/96) (" . " . 104/46 18/58, " . " . 16/65, 54/70
(. . 139/2014)

:
:
:
:
:
:

: JK
:
: . 29, " "
: 07022662
: 100049398
: 105-500122-59

0

10 %
30

XI

57/89, " .46/96) (" . " . 104/46 18/58, " . " . 16/65, 54/70 (. . 139/2014)

:
:
:
:
:
:

: JK
:
: . 29,
: 07022662
: 100049398
: 105-500122-59

0

30 5 %
